



GM NAVIGATION SD CARD

User Manual

2026 Map Edition

For listed GM vehicles with factory Info 3 navigation only.

Setup support

Email: antureofficial@gmail.com

Send your vehicle model, year, and a photo of the screen message.



EMAIL



WHATSAPP

COMPATIBILITY FIRST

Check before installing

1. Confirm your vehicle is on the list below

2. Verify factory Nav icon on your display

3. Confirm there is a built-in SD card slot

Brand		Compatible models & years
BUICK	Enclave	20–24,
	Envision	21–23
CADILLAC	CT4	20–24,
	CT6	19–20,
	XT4	19–23,
	XT6	21–24
CHEVROLET	Blazer	19–24,
	Camaro	19–24,
	Corvette	20–23,
	Malibu	19–24,
	Suburban	2021,
	Traverse	20–24,
GMC	Acadia	20–23,
	Sierra	19–22,
	Yukon	2021
	Canyon	19–22
	Terrain	19–24

North American compatible vehicles only. Vehicle names are used only to identify compatibility. For listed factory-installed navigation systems only. Not compatible with aftermarket or modified head units.

Install in 6 steps

2026

MAP EDITION
DATABASE:
V2025Q2

Map data reflects conditions from approximately 6–12 months prior to release. Some new roads or POIs may not appear.

1

Power off

Keep ignition OFF for at least 10 minutes to allow the system to fully power down.

2

Remove old card

With power OFF, gently push the existing SD card to eject it.

3

Insert new card

Slide the new SD card straight in until it sits firmly.

4

Turn on system

Turn the ignition ON, then launch the navigation system.

5

Confirm prompts

Tap Nav if needed. Press Confirm, then Allow if prompted.

6

Check map

If the navigation map appears, installation is complete.

Important:

The map runs from the SD card and does not download to the vehicle. The About menu version number may not change after installation. Once initialized, the card is VIN-locked and cannot be used in another vehicle.

Quick checks

Message or issue	What to check
SD Card Error / NAV SD Card error	Open the Nav app for details. Make sure the side lock switch is unlocked and UP. Reinsert the card straight into the slot and let the vehicle go to sleep before checking again.
Not valid in this vehicle (error 0x1)	Confirm the card has not been initialized to another VIN. Confirm the vehicle is a listed North American compatible model.
No SD card detected / blank map	Check model year, factory Nav icon, SD card slot, card direction, and firm insertion.
Map looks old / speed limits wrong	Map data is not real-time. Some new roads, POIs, and speed limits may lag because road systems change constantly.
Navigation Service Expired	Try cycling the ignition (turn off, wait, turn on). If the message persists, contact support or your vehicle dealer.

Still stuck? Email antureofficial@gmail.com with vehicle model, year, and screen message.