



MAZDA NAVIGATION SD CARD

User Manual

2026 Map Edition

For listed Mazda Connect navigation-ready vehicles only.
Check model year before installation.

Setup support

Email: antureofficial@gmail.com

Include: model year · card model · screen photo



EMAIL



WHATSAPP

Check your card model

1. Match card model to the label on your card

2. Confirm your vehicle model and year

3. Confirm Mazda Connect system and nav SD slot

Model	Compatible vehicles		
AT-KMV6	CX-5 24–25, CX-90 23–25	CX-30 2024,	Mazda 3 2024
AT-TD2K	CX-5 21–23, CX-9 21–23,	CX-30 21–23, CX-50 22–24,	Mazda 3 21–23 MX-30 22–23
AT-KR9D	CX-50 25–26, CX-90 2026,	CX-30 25–26, CX-70 25–26,	Mazda 3 25–26 MX-5 24–26
AT-BHP1	CX-5 16–20, Mazda 6 16–21,	Mazda 3 16–21, MX-5 16–26,	CX-9 16–21 CX-3 16–21

⚠ 2021 model-year vehicles — check VIN before using AT-TD2K

Vehicle	Build	VIN prefix	From serial	Required card
Mazda 3	MC-built	JM1BP	M1 400001+	AT-TD2K
Mazda 3	MMVO-built	3MZBP	MM 250004+	AT-TD2K
CX-30	—	3MVDM	MM 300002+	AT-TD2K

Install in 6 steps

2026

MAP EDITION
(DATA: 2025 Q2)

North America map coverage includes USA, Canada, and Mexico. Roads, POIs, speed limits, and lane guidance data are updated in cycles, so new local changes may not appear immediately.

1

Power off

Turn the vehicle OFF and wait until the screen and USB indicator are off.

2

Find the slot

Locate the navigation SD slot. Location can vary by model and trim.

3

Remove old card

If a card is installed, press it gently to eject.

4

Insert card

Insert the card straight in. Do not force; if resistance, check orientation.

5

Start vehicle

Turn the vehicle ON, open Navigation or Map, and allow the system to load.

6

Confirm map

If the map appears and route search works, setup is complete.

Important:

Do not format or add files to the card. The system runs from the SD card directly. After first use, the card may lock to one vehicle; do not swap between vehicles.

Quick checks

Message or issue	What to check first
No SD card / blank map	Power off, wait, reinsert firmly. Confirm the vehicle has a navigation-ready SD slot, not only a compass screen.
Invalid card / did not work	Check the table again. Make sure the Anture model, vehicle model, year, and display system match.
2021 Mazda 3 / CX-30	AT-TD2K may need VIN verification. If compatibility is unclear for your 2021 model, send VIN and screen photo to support.
Map outdated / wrong speed limit	Map data is not live traffic. New roads, POIs, and speed limits can lag behind real road changes.
No live traffic / apps	This is a preloaded map SD card only. Live traffic, connected services, and app functions are not included and depend on your vehicle's own setup.
Mazda Toolbox: card not found	Check that the side lock is unlocked. Do not format the card. Contact support if a computer asks to repair it.

Still stuck? Send model year, card model, VIN if requested, and screen photo.
Email antureofficial@gmail.com